

MAIL THE COMPLETED FORM TO: The appropriate EPA Regional or State Office.	United States Environmental Protection Agency RCRA SUBTITLE C SITE IDENTIFICATION FORM <div style="text-align: right;"> REC'D FEB 28 2002 </div>	
1. Reason for Submittal (see instructions on page 10) CHECK CORRECT BOXES	A. Reason for Submittal: <input type="checkbox"/> To provide initial notification (to obtain an EPA ID Number for hazardous waste, universal wastes, or used oil activities). <input type="checkbox"/> To provide subsequent notification (to update site identification information). <input type="checkbox"/> As a component of a First RCRA Hazardous Waste Part A Permit Application. <input type="checkbox"/> As a component of a Revised RCRA Hazardous Waste Part A Permit Application (Amendment #) <input checked="" type="checkbox"/> As a component of Hazardous Waste Report.	
2. Site EPA ID Number (see instructions on page 11)	EPA ID Number: IAD073489288	
3. Site Name (see instructions on page 11)	Site Name: INDUSTRIAL LAMINATES/NORPLEX	
4. Site Location Information (see instructions on page 11)	Street Address: 665 LYBRAND ST P.O. Box 977 City, Town or Village: POSTVILLE State: IA County Name: ALLAMAKEE Zip Code: 521620977	
5. Site Land Type (see instructions on page 11)	Site Land Type: <input checked="" type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other	
6. North American Industry Classification System (NAICS) Code(s) for the Site (see instructions on page 11)	A. 32613	B.
7. Site Mailing Address (see instructions on page 12)	Street or P.O. Box: SAME City, Town or Village: State: Country: UNITED STATES Zip Code:	
8. Site Contact Person (see instructions on page 12)	First Name: SCOTT MI: R Last Name: LOVEN Phone Number: 5638644227 Phone Number Extension:	
9. Legal Owner and Operator of the Site (see instructions on page 12 and 13)	Name of Site's Legal Owner: ISOLA Date Became Owner (mm/dd/yyyy): 01/01/1982 Owner Type: <input checked="" type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other Name of Site's Operator: Industrial Laminates/Norplex Date Became Operator (mm/dd/yyyy): 09/15/1996 Operator Type: <input checked="" type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other	



R00406998

RCRA RECORDS CENTER

Load in BR State
 RCRAIS Data Entered
 By: Tracy / 8
 Date: 06 MAR 2002

10. Type of Regulated Waste Activity (Mark 'X' in the appropriate boxes. See instructions on pages 13, 14, 15 and 16)**A. Hazardous Waste Activities****1. Generator of Hazardous Waste**

(choose one of the following three categories)

- ☒ a. LQG: Greater than 1000 kg/mo (2,200 lbs.) of non-acute hazardous waste; or
- ☐ b. SQG: 100 to 1000 kg/mo (220 - 2,200 lbs.) of non-acute hazardous waste; or
- ☐ c. CESQG: Less than 100 kg/mo of non-acute hazardous waste

In addition, indicate other generator activities (check all that apply)

- ☐ d. United States Importer of Hazardous Waste
- ☐ e. Mixed Waste (hazardous and radioactive) Generator

For items 2 through 6, check all that apply:

- ☐ 2. Transporter of Hazardous Waste
- ☐ 3. Treater, Storer or Disposer of Hazardous Waste (at your site) Note: A hazardous waste permit is required for this activity.
- ☐ 4. Recycler of Hazardous Waste (at your site) Note: A hazardous waste permit may be required for this activity.
5. Exempt Boiler and/or Industrial Furnace
- ☐ a. Small Quantity On-Site Burner Exemption
- ☐ b. Smelting, Melting, Refining Furnace Exemption
- ☐ 6. Underground Injection Control

B. Universal Waste Activities**1. Large Quantity Handler of Universal Waste (refer to your State regulations to determine what is regulated). Indicate types of universal waste generated and/or accumulated at your site. (check all boxes that apply):**

	<u>Generated</u>	<u>Accumulated</u>
a. Batteries	<input type="checkbox"/>	<input type="checkbox"/>
b. Pesticides	<input type="checkbox"/>	<input type="checkbox"/>
c. Thermostats	<input type="checkbox"/>	<input type="checkbox"/>
d. Lamps	<input type="checkbox"/>	<input type="checkbox"/>
e. Other (specify)	<input type="checkbox"/>	<input type="checkbox"/>
f. Other (specify)	<input type="checkbox"/>	<input type="checkbox"/>
g. Other (specify)	<input type="checkbox"/>	<input type="checkbox"/>

☐ 2. Destination Facility for Universal Waste

Note: A hazardous waste permit may be required for this activity.

C. Used Oil Activities**1. Used Oil Transporter - Indicate type(s) of activity(ies)**

- ☐ a. Transporter
- ☐ b. Transfer Facility

2. Used Oil Processor and/or Re-refiner - Indicate Type(s) of Activity(ies)

- ☐ a. Processor
- ☐ b. Re-refiner

☐ 3. Off-Specification Used Oil Burner**4. Used Oil Fuel Marketer - Indicate Type(s) of Activity(ies)**

- ☐ a. Marketer Who Directs Shipment of Off-Specification Used Oil to Off-Specification Used Oil Burner
- ☐ b. Marketer Who First Claims the Used Oil Meets the Specifications

11. Description of Hazardous Wastes (see instructions on page 16)**A. Waste Codes for Federally Regulated Hazardous Wastes.** Please list the waste codes of the Federal hazardous wastes handled at your site. List them in the order they are presented in the regulations (e.g., D001, D003, F007, U112). Use an additional page if more spaces are needed.

D001	D007	D008	D039	F003	F005	U002
U122	U188					


EPA ID No. IAD073489288

B. Waste Codes for State-Regulated (i.e., non-Federal) Hazardous Wastes. Please list the waste codes of the State-regulated hazardous wastes handled at your site. List them in the order they are presented in the regulations. Use an additional page if needed for more waste codes.

12. Comments (see instructions on page 17)

ISOLA SOLD THE BUSINESS TO INDUSTRIAL DIELECTRICS IN 1997. ISOLA RETAINED OWNERSHIP OF THE LAND AND THE BUILDING. DATE OF ISOLA'S PROPERTY OWNERSHIP IS UNCERTAIN, BUT BELIEVED TO BE 1982.

13. Certification. I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (see instructions on page 17)

Signature of owner, operator, or an authorized representative	Name and Official Title (type or print)	Date Signed (mm/dd/yyyy)
	JIM GILBERT, PLANT MANAGER	02/22/2002

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: INDUSTRIAL LAMINATES/NORPLEX

EPA ID NO: IAD073489288



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number of instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste Description (page 22) Still bottoms from solvent recovery batch distillation unit.				
B. EPA Hazardous Waste Codes (page 22)		F003	F005	C. State Hazardous Waste Codes (page 22)	
NA		NA	NA		
D. Source Code (page 23)	G24	E. Form Code (page 23)		F. RCRA Radioactive Mixed (page 23)	
Management Method Code for Source Code G25		W200			
				G. Quantity Generated in 2001 (page 22)	H. UOM (page 23)
				7,593.000000	1
					Density
					<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? (page 24)	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code (page 24)	Quantity treated, disposed or recycled on-site in 2001 (page 25)	On-site Management Method Code (page 24)
		Quantity treated, disposed or recycled on-site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off-site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	MND000686709	H061	7,593.000000
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: INDUSTRIAL LAMINATES/NORPLEX

EPA ID NO: IAD073489288



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number of instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste Description (page 22) Ignitable resin/solvent mixture remaining from process clean-up				
B. EPA Hazardous Waste Codes (page 22)		D001	F003	C. State Hazardous Waste Codes (page 22)	
NA		NA	NA		
D. Source Code (page 23)		G13	E. Form Code (page 23)	F. RCRA Radioactive Mixed (page 23)	G. Quantity Generated in 2001 (page 22)
Management Method Code for Source Code G25			W203	<input type="checkbox"/> Yes	181,176.000000
					H. UOM (page 23) Density
					1 <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? (page 24)	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)		
<input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code (page 24)	Quantity treated, disposed or recycled on-site in 2001 (page 25)	On-site Management Method Code (page 24)
		Quantity treated, disposed or recycled on-site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off-site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	MND000686709	H061	178,426.000000
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	WID023350192	H020	2,750.000000
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: INDUSTRIAL LAMINATES/NORPLEX

EPA ID NO: IAD073489288



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number of instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste Description (page 22) Ignitable liquid; mixture contains rags, resin, and solvent from clean-up				
	B. EPA Hazardous Waste Codes (page 22) D001 F003 F005 NA NA		C. State Hazardous Waste Codes (page 22)		
D. Source Code (page 23) G13 Management Method Code for Source Code G25	E. Form Code (page 23) W002	F. RCRA Radioactive Mixed (page 23) <input type="checkbox"/> Yes	G. Quantity Generated in 2001 (page 22) 3,390.000000	H. UOM (page 23) Density 1 <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1	ON-SITE PROCESS SYSTEM 2
	On-site Management Method Code (page 24)	Quantity treated, disposed or recycled on-site in 2001 (page 25)
	On-site Management Method Code (page 24)	Quantity treated, disposed or recycled on-site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off-site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped (page 26) MND000686709	C. Off-site Management Method Code Shipped to (page 26) H061	D. Total quantity shipped in 2001 (page 26) 3,390.000000
	Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: INDUSTRIAL LAMINATES/NORPLEX

EPA ID NO: IAD073489288



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

2001 Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number of instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste Description (page 22) Melamine resin/solvent and water remainder from melamine treater clean-up				
B. EPA Hazardous Waste Codes (page 22)		D001	F003	C. State Hazardous Waste Codes (page 22)	
		F005	NA		
D. Source Code (page 23)		G13	E. Form Code (page 23)	F. RCRA Radioactive Mixed (page 23)	G. Quantity Generated in 2001 (page 22)
		Management Method Code for Source Code G25	W113		21,383.000000
				<input type="checkbox"/> Yes	H. UOM (page 23) Density 1 <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? (page 24)			
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code (page 24)		Quantity treated, disposed or recycled on-site in 2001 (page 25)		On-site Management Method Code (page 24)
				Quantity treated, disposed or recycled on-site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off-site in 2001 for treatment, disposal or recycling? (pages 25 and 26)			
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)				
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)	
	MND000686709	H061	21,383.000000	
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)	
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)	

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: INDUSTRIAL LAMINATES/NORPLEX

EPA ID NO: IAD073489288



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number of instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste Description (page 22) Drum resin that has set-up, and become a solid.				
B. EPA Hazardous Waste Codes (page 22)		D001	F003	C. State Hazardous Waste Codes (page 22)	
		F005	NA	NA	
D. Source Code (page 23)		G11	E. Form Code (page 23)	F. RCRA Radioactive Mixed (page 23)	G. Quantity Generated in 2001 (page 22)
		Management Method Code for Source Code G25	W403		3,390.000000
				<input type="checkbox"/> Yes	H. UOM (page 23) 1 Density
					<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? (page 24)	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code (page 24)	Quantity treated, disposed or recycled on-site in 2001 (page 25)	On-site Management Method Code (page 24) Quantity treated, disposed or recycled on-site in 2001 (page 25)

Sec. 3	A. Was any of this waste shipped off-site in 2001 for treatment, disposal or recycling? (pages 25 and 26)		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
	MND000686709	H061	3,390.000000
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: INDUSTRIAL LAMINATES/NORPLEX

EPA ID NO: IAD073489288



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number of instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste Description (page 22) Ignitable solvent used for parts washer, contains petroleum naptha				
B. EPA Hazardous Waste Codes (page 22) D039 NA NA NA NA		C. State Hazardous Waste Codes (page 22)			
D. Source Code (page 23) G01 Management Method Code for Source Code G25		E. Form Code (page 23) W203	F. RCRA Radioactive Mixed (page 23) <input type="checkbox"/> Yes	G. Quantity Generated in 2001 (page 22) 30.000000	H. UOM (page 23) 5 Density 7.00 <input checked="" type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2	
On-site Management Method Code (page 24)		On-site Management Method Code (page 24)	
Quantity treated, disposed or recycled on-site in 2001 (page 25)		Quantity treated, disposed or recycled on-site in 2001 (page 25)	

Sec. 3	A. Was any of this waste shipped off-site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26) WID980896641	C. Off-site Management Method Code Shipped to (page 26) H020	D. Total quantity shipped in 2001 (page 26) 30.000000
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: INDUSTRIAL LAMINATES/NORPLEX

EPA ID NO: IAD073489288



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

2001 Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form. In addition, the page number of instructions specific to each box is provided in parentheses.

Sec. 1	A. Waste Description (page 22) Ignitable water solvent mixture from contaminated groundwater				
B. EPA Hazardous Waste Codes (page 22) D001 D007 D008 F003 F005		C. State Hazardous Waste Codes (page 22)			
D. Source Code (page 23) G45 Management Method Code for Source Code G25		E. Form Code (page 23) W113	F. RCRA Radioactive Mixed (page 23) <input type="checkbox"/> Yes	G. Quantity Generated in 2001 (page 22) 5,400.000000	
H. UOM (page 23) Density 5 8.00 <input checked="" type="checkbox"/> lbs/gal <input type="checkbox"/> sg					

Sec. 2	Was any of this waste managed on-site? (page 24) <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2	
On-site Management Method Code (page 24)		On-site Management Method Code (page 24)	
Quantity treated, disposed or recycled on-site in 2001 (page 25)		Quantity treated, disposed or recycled on-site in 2001 (page 25)	

Sec. 3	A. Was any of this waste shipped off-site in 2001 for treatment, disposal or recycling? (pages 25 and 26) <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped (page 26) OHD093945293	C. Off-site Management Method Code Shipped to (page 26) H134	D. Total quantity shipped in 2001 (page 26) 5,400.000000
Site 2	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)
Site 3	B. EPA ID No. of facility to which waste was shipped (page 26)	C. Off-site Management Method Code Shipped to (page 26)	D. Total quantity shipped in 2001 (page 26)

Comments: